



Dave Heineman
Governor

State of Nebraska

DEPARTMENT OF AGRICULTURE
GREGORY A. IBACH
Director

Nebraska Standards Laboratory
3721 West Cuming Street
Lincoln, NE 68524

CERTIFICATION FOR STANDARDS OF MEASUREMENT

Agency: Dept of Ag. - Weights & Measures
84627 550th Ave.
Norfolk, NE 68701-

Date: 10/27/2009
Agency ID: 10
NE Cert No: 20090145
P.O. No:

Submitted By: Eugene Haase

Electronic Copy Page 1

<u>Denomination</u>	<u>Serial Number</u>	<u>Weight Number</u>	<u>Tolerance Class</u>
50 lb	C-C1	1	F
50 lb	C-C10	1	F
50 lb	C-C13	1	F
50 lb	C-C14	1	F
50 lb	C-C15	1	F
50 lb	C-C16	1	F
50 lb	C-C17	1	F
50 lb	C-C18	1	F
50 lb	C-C19	1	F
50 lb	C-C2	1	F
50 lb	C-C3	1	F
50 lb	C-C4	1	F
50 lb	C-C5	1	F
50 lb	C-C6	1	F
50 lb	C-C8	1	F
2 kg	K1	1	F
50 lb	OPI-C62	1	F
50 lb	OPI-C89	1	F
25 lb	WM25-24	1	F
1 kg	WM-2-89-5	1	F
500 g	WM-2-89-5	2	F
200 g	WM-2-89-5	3	F
200 g*	WM-2-89-5	4	F
100 g	WM-2-89-5	5	F
50 g	WM-2-89-5	6	F

Department of Agriculture, 301 Centennial Mall South
Web Site: www.agr.ne.gov

Administration
P.O. Box 94947
Lincoln, NE 68509-4947
(402) 471-2341
FAX: (402) 471-6876

Agriculture Laboratories
3703 South 14th Street
Lincoln, NE 68502-5399
(402) 471-2176
FAX: (402) 471-0091

Bureau of Animal Industry
P.O. Box 94987
Lincoln, NE 68509-4787
(402) 471-2351
FAX: (402) 471-6893

Bureau of Dairies & Foods
P.O. Box 95064
Lincoln, NE 68509-5064
(402) 471-2536
FAX: (402) 471-2759

Bureau of Plant Industry
P.O. Box 94956
Lincoln, NE 68509-4756
(402) 471-2394
FAX: (402) 471-6892

Weights and Measures
P.O. Box 94757
Lincoln, NE 68509-4757
(402) 471-4292
FAX: (402) 471-2759

Submitted By: Eugene Haase

Electronic Copy

Page 2

<u>Denomination</u>	<u>Serial Number</u>	<u>Weight Number</u>	<u>Tolerance Class</u>
20 g	WM-2-89-5	7	F
20 g*	WM-2-89-5	8	F
10 g	WM-2-89-5	9	F
5 g	WM-2-89-5	10	F
2 g	WM-2-89-5	11	F
2 g*	WM-2-89-5	12	F
1 g	WM-2-89-5	13	F
500 mg	WM-2-89-5	14	F
200 mg	WM-2-89-5	15	F
200 mg*	WM-2-89-5	16	F
100 mg	WM-2-89-5	17	F
5 lb	WM-2C86	1	F
5 lb	WM-2C86	2	F
5 lb	WM-2C86	3	F
5 lb	WM-2C86	4	F
5 lb	WM-2C86	5	F
1 lb	WM-2C86	6	F
1 lb	WM-2C86	7	F
1 lb	WM-2C86	8	F
1 lb	WM-2C86	9	F
1 lb	WM-2C86	10	F
8 oz	WM-2C86	11	F
4 oz	WM-2C86	12	F
2 oz	WM-2C86	13	F
1 oz	WM-2C86	14	F
0.5 oz	WM-2C86	15	F
0.25 oz	WM-2C86	16	F
0.125 oz	WM-2C86	17	F
0.0625 oz	WM-2C86	18	F
50 lb	WM50-42	1	F
50 lb	WM50-48	1	F
50 lb	WM50-71	1	F
25 lb	WM-D51	1	F
25 lb	WM-D52	1	F
25 lb	WM-D53	1	F
25 lb	WM-D54	1	F

Submitted By: Eugene Haase

Electronic Copy

Page 3

Denomination	Serial Number	Weight Number	Tolerance Class
25 lb	WM-D55	1	F
25 lb	WM-D56	1	F
25 lb	WM-D57	1	F
25 lb	WM-D58	1	F
25 lb	WM-D59	1	F
25 lb	WM-D60	1	F
25 lb	WM-D61	1	F
1000 lb	WME1	1	F
1000 lb	WME10	1	F
1000 lb	WME11	1	F
1000 lb	WME12	1	F
1000 lb	WME13	1	F
1000 lb	WME14	1	F
1000 lb	WME15	1	F
1000 lb	WME17	1	F
1000 lb	WME19	1	F
1000 lb	WME2	1	F
1000 lb	WME20	1	F
1000 lb	WME21	1	F
1000 lb	WME22	1	F
1000 lb	WME23	1	F
1000 lb	WME24	1	F
1000 lb	WME3	1	F
1000 lb	WME4	1	F
1000 lb	WME5	1	F
1000 lb	WME6	1	F
1000 lb	WME7	1	F
1000 lb	WME9	1	F

These field standards have been compared with our reference standards and found to be within the tolerances for their class, or condemned, as prescribed by the National Institute of Standards and Technology. These field standards also meet the required specifications.

The reference standards used are traceable to the National Institute of Standards and Technology (NIST). Our traceability is maintained through control charts, regional inter-comparisons and periodic recertifications. This certificate is issued by the Nebraska Department of Agriculture / Division of Weights and Measures. Reproduction of this certificate must include the entire document (including all attached papers).

See 'Test Results' attached

See report/letter attached



Craig E. Olsen

Nebraska State Metrologist